


DEVELOPMENT OF THE FARM OUTENIKUASBOSCH 149 AND PART 10 & 28 OF THE FARM HARTENBOSCH217

TEST PIT F



Comments :

No seepage water was observed.
No refusal in test pit.
Excavation method : CAT digger loader.
Date of excavation : 05 October 2018.



RoadLab MossLab JV

CIVIL ENGINEERING MATERIALS LABORATORY

7 BALLY CRESCENT, VOORBAAI, MOSSEL BAY
P.O. BOX 35, HARTENBOS, 6520
TEL. : (044) 6952387
CELL : 0829287562