


GEOTECHNICAL INVESTIGATION

OUTENIKUASBOSCH PHASE 12 & 14, HARTENBOS

TEST PIT 1 (PHASE 12): PROFILE



Comments :

No seepage water was observed.
No refusal in test.
Excavation method : Tracked Excavator
Date of excavation : 23 January 2023