


GEOTECHNICAL INVESTIGATION

OUTENIKUASBOSCH PHASE 12 & 14, HARTENBOS

TEST PIT 2 (PHASE 12): PROFILE



Comments :

No seepage water was observed.

No refusal in test.

Excavation method : Tracked Excavator

Date of excavation : 12 January 2023



TESTPRO LABORATORY
Materials Testing Laboratory