


GEOTECHNICAL INVESTIGATION OUTENIQUASBOSCH PHASE 9, HARTENBOS

TEST PIT 3 : PROFILE



Comments :

No seepage water was observed.
No refusal in test pit.
Excavation method : Tracked Excavator
Date of excavation : 18 September 2023



TESTPRO LABORATORY
Materials Testing Laboratory