


GEOTECHNICAL INVESTIGATION OUTENIQUASBOSCH PHASE 11 & 13, HARTENBOS

TEST PIT 1 : PROFILE



Comments :

No seepage water was observed.
No refusal in test.
Excavation method : Digger Loader
Date of excavation : 27 April 2022



TESTPRO LABORATORY
Materials Testing Laboratory