


GEOTECHNICAL INVESTIGATION OUTENIQUASBOSCH PHASE 11 & 13, HARTENBOS

TEST PIT 4 : PROFILE



Comments :

No seepage water was observed.
Partial refusal in test at NGL -1600mm.
Excavation method : Digger Loader
Date of excavation : 27 April 2022