


GEOTECHNICAL INVESTIGATION OUTENIQUASBOSCH PHASE 4, HARTENBOS

TEST PIT 3 : PROFILE



Comments :

No seepage water was observed.
Partial refusal in test pit at NGL -1620mm.
Excavation method : Digger Loader
Date of excavation : 4 May 2022



TESTPRO LABORATORY
Materials Testing Laboratory