


GEOTECHNICAL INVESTIGATION OUTENIKUASBOSCH PHASE 7, HARTENBOS

TEST PIT 1 : PROFILE



Comments :

No seepage water was observed.
No refusal in test pit.
Excavation method : Tracked excavator
Date of excavation : 4 February 2025