


GEOTECHNICAL INVESTIGATION OUTENIKUASBOSCH PHASE 7, HARTENBOS

TEST PIT 2 : PROFILE



Moist, redish brown, medium dense, firm, medium coarse intact transported sandy clayey topsoil. No sample. In Situ moisture content = 15.6%

Moist, yellowish white, medium dense, firm, fine intact residual silty sandy clay. Sample no 4447. In situ moisture content = 11.6%

Comments :

No seepage water was observed.
No refusal in test pit.
Excavation method : Tracked excavator
Date of excavation : 4 February 2025